

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



REGULATORY DOCKET FILE COPY

May 16, 1978
IP-JWK-1781


Re: Docket No. 50-286

Mr. Boyce Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Report LER 78-008/3L-0 is hereby submitted for your information. It should be noted, however, that the remaining two charging pumps were operable per Technical Specifications 3.2.B.1. Had the third pump been required to be operable, its failure would be reportable in accordance with the requirements of 6.9.1.8.b.

Very truly yours,


J. P. Bayne
Resident Manager

JWK/rbb

cc: Director of Nuclear Reactor Regulation
Attn: Mr. William McDonald, Director (2 copies)
Office of Management Information & Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dr. Ernst Volgenau (40 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

8111070130 780516
PDR ADOCK 05000286
S PDR

781370010

RECEIVED DISTRIBUTION
SERVICES UNIT

US NRC
DISTRIBUTION SERVICES
BRANCH

1978 MAY 16 AM 10 51

A002
5/11