

POWER AUTHORITY OF THE STATE OF NEW YORK  
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



REGULATORY DOCKET FILE COPY

May 16, 1978  
IP-JWK-1781

Re: Docket No. 50-286

Mr. Boyce Grier, Director  
Office of Inspection and Enforcement  
Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Report LER 78-008/3L-0 is hereby submitted for your information. It should be noted, however, that the remaining two charging pumps were operable per Technical Specifications 3.2.B.1. Had the third pump been required to be operable, its failure would be reportable in accordance with the requirements of 6.9.1.8.b.

Very truly yours,

J. P. Bayne  
Resident Manager

JWK/rbb

cc: Director of Nuclear Reactor Regulation  
Attn: Mr. William McDonald, Director (2 copies)  
Office of Management Information & Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dr. Ernst Volgenau (40 copies)  
Office of Inspection and Enforcement  
c/o Distribution Services Branch, DDC,ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, New York 10019

US NRC  
DISTRIBUTION SERVICES  
BRANCH

1978 MAY 16 AM 10 51

RECEIVED DISTRIBUTION  
SERVICES UNIT

781370010

8111070130 780516  
PDR ADOCK 05000286  
S PDR

A002  
5/11