

NUCLEAR EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 N Y I P S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 8 6 7 0 1 2 4 7 8 8 0 2 2 3 7 8 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 During normal operation, the 13.8 KV gas turbine substation transformer
0 3 breaker GT-2F tripped due to the activation of the transformer protective
0 4 relays, rendering the 13.8 KV feed to the unit unavailable. All three
0 5 emergency diesel generators were tested and verified operable, and a
0 6 13.8 KV source of power was restored within the time limit permitted by
0 7 Technical Specification 3.7.B.2. This occurrence is reportable under
0 8 the provisions of Technical Specification 3.7.A.3.

0 9 SYSTEM CODE E A 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE E I E C O I N 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 7 8 EVENT YEAR 0 0 2 SEQUENTIAL REPORT NO. 0 3 OCCURRENCE CODE L REPORT TYPE 0 REVISION NO.
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN B 18 FUTURE ACTION X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUR. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER Z 9 9 9
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 A 13.8 KV source of power was lost to the station as a result of a flash-
1 1 over on a bus duct joint, apparently caused by moisture collection.
1 2 The affected joints were cleaned and taped, and 13.8 KV power was re-
1 3 stored. Additional bus joints will be inspected and sealed, if neces-
1 4 sary, during the forthcoming refueling outage.

1 5 FACILITY STATUS E 28 % POWER 0 9 1 29 OTHER STATUS NA METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Control Room Alarm, Operator Ob-
7 8 9 10 12 13 44 45 46 80 servation
1 6 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA
7 8 9 10 11 44 45 80
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 11 12 13 80
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 11 12 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 11 12 80

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 80
8111070186 780223 PDR ADOCK 05000286 S PDR
NRC USE ONLY
John M. Makepeace PHONE: 914-739-8823