

LICENSEE EVENT REPORT

R.O.-77-3-7(B)

CONTROL BLOCK:

1. PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME

LICENSE NUMBER

LICENSE TYPE

EVENT TYPE

01 N Y I P S 3 |
 0 0 - 0 0 0 0 0 0 - 0 0 |
 4 1 Y 1 1 |
 0 3

01 CONT |
 |
 L |
 L |
 0 5 0 - 0 2 8 6 |
 0 7 1 3 7 7 |
 0 8 0 4 7 7

EVENT DESCRIPTION

02 While at hot shutdown following a unit trip, outside power to the sta-
03 tion was lost. Emergency Diesel Generators started and assumed 480 V
04 bus loads as required. The loss of outside power was the result of
05 severe electrical storms which rendered a number of system transmission
06 lines inoperable. Outside power was restored to the station within the

SYSTEM CODE: E A |
 CAUSE CODE: C |
 COMPONENT CODE: Z Z Z Z Z Z |
 HOME COMPONENT SUPPLIER: Z |
 COMPONENT MANUFACTURER: Z 9 9 9 |
 VIOLATION: N

CAUSE DESCRIPTION

08 This event was precipitated by a series of lightning strikes, resulting
09 in a loss of outside power to the station.

FACILITY STATUS: G |
 % POWER: 0 0 0 |
 OTHER STATUS: NA |
 METHOD OF DISCOVERY: A |
 DISCOVERY DESCRIPTION: NA

FORM OF ACTIVITY RELEASED: Z |
 CONTENT OF RELEASE: Z |
 AMOUNT OF ACTIVITY: NA |
 LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

13 NUMBER: 0 0 0 |
 TYPE: Z |
 DESCRIPTION: NA

PERSONNEL INJURIES

14 NUMBER: 0 0 0 |
 DESCRIPTION: NA

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z |
 DESCRIPTION: NA

PUBLICITY

17 Extensive media coverage of subsequent system blackout.

ADDITIONAL FACTORS

18 (Event Description Continued) - required Tech. Spec. time limit.

18 [R.O.-77-3-7(B)].

8111070235 770804
 PDR ADOCK 05000286
 S PDR