

LICENSEE EVENT REPORT

TEIR-77-3-3

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE				EVENT TYPE	
01	N	Y	I	P	S	3	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	9	9							
7	8	9	14	15	25	26	30	31	32																						
01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE				REPORT DATE											
01	7	8	57	58	59	60	61	68	69	74	75	80																			

EVENT DESCRIPTION

02	FOR INFORMATION ONLY. During startup operations, an attempt to put No.																																																																															
03	33 motor driven auxiliary boiler feed pump into service was unsuccessful																																																																															
04	Steam generator levels were maintained utilizing No. 31 and 32 auxiliary																																																																															
05	boiler feed pumps. No. 33 auxiliary boiler feed pump was removed from																																																																															
06	service for investigation and repair. [TEIR-77-3-3].																																																																															

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	H	H	E	P	U	M	P	X	X	N	I	0	7	5	N
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

CAUSE DESCRIPTION

08	Upon investigation, it was found that the shaft of an Ingersoll-Rand																																																																															
09	pump, Model No. 3HMTA-9 had sheared. Repairs to the pump will be com-																																																																															
10	pleted upon receipt and installation of required replacement parts.																																																																															

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	C	0	0	0	NA	A	NA		
7	8	9	10	11	12	13	14	15	16
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z	NA	NA					
7	8	9	10	11	12	13	14	15	16

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	NA
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION		
14	0	0	0	NA
7	8	9	11	12

PROBABLE CONSEQUENCES

15	NA																																																																															
7	8	9																																																																														

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	NA	
7	8	9	10

PUBLICITY

17	NA																																																																															
7	8	9																																																																														

ADDITIONAL FACTORS

18	NA																																																																															
7	8	9																																																																														

19																																																																																
7	8	9																																																																														

8111070270 770517
PDR ADOCK 05000286
S PDR

NAME: John M. Makepeace

PHONE: 914-739-8823

RECEIVED
U.S.N.R.C.

MAY 19 1977

OF PRUSSIA

RECEIVED DOCUMENT
PROCESSING UNIT

1977 MAY 24 AM 10 40