


William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-3819

REGULATORY DOCKET FILE COPY



October 20, 1976

Re: Indian Point Unit No. 3
Docket No. 50-286
R.O. -76-3-30(A) - Update Report

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, Pa. 19406



Dear Mr. O'Reilly:

Attached is an update report for Reportable Occurrence R.O. -76-3-30(A) which revises the cause code, component manufacturer, cause description and event description contained in the previous report submitted on August 30, 1976.

Three copies of this letter and the attachment are also enclosed.

Very truly yours,

William J. Cahill, Jr.
Vice President

Enc:
PK/mmg

Copy to : Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (40 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N.Y. 10019

8111070445 761020
PDR ADOCK 05000286
S PDR

10885

