

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

July 22, 1976

Re: Indian Point Unit No. 3
Docket No. 50-286
R.O. -76-3-24(B)



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406

Dear Mr. O'Reilly:

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64 the attached report of Reportable Occurrence R.O. -76-3-24(B) is submitted. This report fulfills the requirement for a written report within 30 days of a Reportable Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours

William Cahill, Jr.
William J. Cahill, Jr.
Vice President


mw
Attachment

Copies to: Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control

U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N.Y. 10019



Regulatory Docket File

8111070506 760722
PDR ADOCK 05000286
PDR

