Consolidated Edison Company of New York, Inc.

4 Irving Place, New YORK N Y Telephone (21,2

Regulatory Dochel File July 8, 1976

Indian Point Unit No. 3 Re: Docket No. 50-286

R.O. -76-3-17(B)

-76-3-18(B)

-76-3-19(B)

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement Region 1 U.S. Nuclear Regulatory Commission King of Prussia, Penn. 19406

Dear Mr. O'Reilly:

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64, the attached reports of Reportable Occurrences R.O. -76-3-17(B), R.O. -76-3-18(B) and R.O. -76-3-19(B) are submitted. These reports fulfill the requirement for written reports within 30 days of Reportable Occurrences and are in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachments are enclosed as required.

Very truly yours,

William J. Cahill, Jr.

Vice President

enc. mw

Copies to: Director of Nuclear Reactor Regulation ATTN: Dr. Ernst Volgenau, Director (30 copies) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission

Washington, D.C. 20555

Director of Nuclear Reactor Regulation

Mr. William G. McDonald, Director (3 copies)

Office of Management Information and

Program Control

U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Mr. George T. Berry General Manager and Chief Engineer Power Authority of the State of New York 10 Columbus Circle

New York, N.Y. 10019