


Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N. Y. 10003
Telephone (212) 460-5133

July 2, 1976

Re: Indian Point Unit No. 3
Docket No. 50-286
R.O. -76-3-15(B)
-76-3-16(B)

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
King of Prussia, Penn. 19406



Dear Mr. O'Reilly:

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64, the attached reports of Reportable Occurrences R.O. -76-3-15(B) and R.O. -76-3-16(B) are submitted. These reports fulfill the requirement for written reports within 30 days of Reportable Occurrences and are in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachments are enclosed as required.

Very truly yours,

Carl L. Newman

Carl L. Newman
Vice President

enc.
mw


Copies to: Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (30 copies)
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Regulatory Docket File

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

6760

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N.Y. 10019



8111070541 760702
PDR ADOCK 05000286
S PDR