

POWER AUTHORITY OF THE STATE OF NEW YORK

INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



REGULATORY DOCKET FILE COPY

September 29 1978
IP-FWG-2984

Docket No. 50-286

RECEIVED DISTRIBUTION SERVICES UNIT
1978 OCT 14 AM 11 41
REGULATORY SERVICES BRANCH

Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Report LER 78-029/03L-0 is hereby submitted for your information. It should be noted, however, that one level transmitter was operable as per Technical Specification 3.3.A.1.d. Had this transmitter not been available, the event would be reportable in accordance with requirements of 6.9.1.8.(b).

Very truly yours,

J. P. Bayne
Resident Manager

REGULATORY DOCKET FILE COPY

FWG/rbb
Attachment

cc: Director of Nuclear Reactor Regulation
Attn: William McDonald, Director (3 copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Office of Inspection and Enforcement (30 copies)
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

Resident Inspector T. Rebelowski
George Wilverding, NYO
P. W. Lyon, NYO
James Davis (SRC), NYO

780660239

A002/S*
1/30

8111090158 780929
PDR ADOCK 05000286
S PDR