

POWER AUTHORITY OF THE STATE OF NEW YORK

INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



REGULATORY DOCKET FILE COPY

September 25, 1978  
IP-FWG-2952

Re: Docket No. 50-286

1978 SEP 27 PM 9 15  
REGULATORY SERVICES  
DISTRIBUTION UNIT

Boyce H. Grier, Director  
Office of Inspection and Enforcement  
Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Report LER 78-024/03L-0 is hereby submitted for your information. It should be noted, however, that sufficient auxiliary boiler feed pumps were available as per Technical Specification 6.9.1. Had an insufficient number of auxiliary boiler feed pumps been available, the event would be reportable in accordance with requirements of 6.9.1.8.(b).

Very truly yours,

J. P. Bayne  
Resident Manager

FWG/rbb  
Attachment

cc: Director of Nuclear Reactor Regulation  
Attn: William McDonald, Director (3 copies)  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Office of Inspection and Enforcement  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, New York 10019

Resident Inspector T. Rebelowski  
George Wilverding, NYO  
P. W. Lyon, NYO  
James Davis (SRC), NYO

782020348

8111090256 780925  
PDR ADOCK 05000286  
S PDR

App 2  
5/11