

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200

REGULATORY DOCKET FILE COPY



August 24, 1978

IP-NAP-2467

U.S. NRC
REGULATORY
SERVICES
BRANCH

1978 AUG 28 PM 12 00

RECEIVED DISTRIBUTION
SERVICES UNIT

Mr. Boyce Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Update Report LER 78-016/03L-1 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.8.(a). The event occurred as a result of a periodically tested equipment setting deviating from required tolerance.

Very truly yours,

J. P. Bayne
Resident Manager

NAP/bal

cc: Director of Nuclear Reactor Regulation
Attn: Mr. Willaim McDonald, Director (3 copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. Ernst Volgenau (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

782370300

8111090353 780824
PDR ADOCK 05000286
S PDR

Aug 28
S
11