

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
0 1 N Y I P S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 8 6 7 0 7 1 5 7 8 8 0 8 1 5 7 8 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While shutdown for refueling, performance of Refueling Test, 3PC-R1(A),
0 3 showed reactor coolant loop temperature transmitters TE-421B and TE-441A
0 4 to be outside the required tolerance.
0 5
0 6
0 7
0 8

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
0 9 SYSTEM CODE C B (11) CAUSE CODE E (12) CAUSE SUBCODE E (13) COMPONENT CODE I N S T R U (14) COMP. SUBCODE T (15) VALVE SUBCODE Z (16)
LER/RO REPORT NUMBER (17) EVENT YEAR 7 8 (21) SEQUENTIAL REPORT NO. 0 1 7 (24) OCCURRENCE CODE 0 3 (28) REPORT TYPE L (30) REVISION NO. 0 (32)
ACTION TAKEN E (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. N (24) PRIME COMP. SUPPLIER N (25) COMPONENT MANUFACTURER F 1 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Foxboro Model 694A temperature transmitters were found to be
1 1 outside the required tolerance and were recalibrated.
1 2
1 3
1 4

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 5 FACILITY STATUS H (28) % POWER 0 0 0 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION Surveillance Test (32)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 6 ACTIVITY CONTENT Z (33) RELEASED OF RELEASE Z (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION NA (39)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 8 PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION NA (41)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION NA (43)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
2 0 PUBLICITY ISSUED N (44) DESCRIPTION NA (45)

8111090400 780815
PDR ADOCK 05000286
S PDR

NRC USE ONLY
80