

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



REGULATORY DOCKET FILE COPY

June 7, 1978

IP-NAP-1942

Mr. Boyce Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406



Dear Mr. Grier:

The attached Licensee Event Report LER 78-011/3L-0 is hereby submitted for your information. It should be noted, however, that sufficient Auxiliary Boiler Feed Pumps and associated valves were operable as per Technical Specification 3.4.A.2 and 3.4.A.4. Had an insufficient number of valves or pumps been available, the event would be reportable in accordance with requirements of 6.9.1.8 (b).

Very truly yours,


J. P. Bayne
Resident Manager

NAP/rbb

cc: Director of Nuclear Reactor Regulation
Attn: Mr. William McDonald, Director (2 copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. Ernst Volgenau (40 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

781650248

8111100113 780607
PDR ADOCK 05000286
S PDR

A002/S *
1/1