

POWER AUTHORITY OF  
10 COLUMBUS CIRCLE  
(212) 397-6200

REGULATORY BOOKET FILE COPY  
NEW YORK

NEW YORK, N. Y. 10019

TRUSTEES  
FREDERICK R. CLARK  
CHAIRMAN  
GEORGE L. INGALLS  
VICE CHAIRMAN  
RICHARD M. FLYNN  
ROBERT I. MILLONZI  
WILLIAM F. LUDDY



June 9, 1978  
IPO-116

GEORGE T. BERRY  
GENERAL MANAGER  
AND CHIEF ENGINEER  
LEWIS R. BENNETT  
ASSISTANT GENERAL  
MANAGER-GENERAL  
COUNSEL  
WILBUR L. GRONBERG  
ASSISTANT GENERAL  
MANAGER-ENGINEERING  
JOHN W. BOSTON  
DIRECTOR OF  
POWER OPERATIONS  
THOMAS F. MCCRANN, JR.  
CONTROLLER

Director of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Mr. Albert Schwencer, Chief  
Operating Reactors Branch No. 1

Subject: Indian Point 3 Nuclear Power Plant  
Docket No. 50-286



Dear Mr. Schwencer:

By letter dated February 27, 1978 Consolidated Edison Company of New York, Inc. requested an extension for the submittal of information requested by your letters of September 14 and October 27, 1977 relative to lamellar tearing of Steam Generator and Reactor Coolant Pump supports.

At that time, it was anticipated that responses to your questions could be provided by June 1, 1978; however, our NSSS vendor will now provide us with a compilation of plant data in September, 1978. It is now expected that responses can be submitted by September 29, 1978.

Very truly yours,

  
P. J. Early  
Assistant Chief Engineer-  
Projects

781650019

8111120351 780609  
PDR ADOCK 05000286  
P PDR

A018/s \*  
110

5 NUCLEAR REGULATORY COMMISSION  
6 DAILY ACCESSION LIST

05/10/78

PAGE 29  
FILE LOCATION

13  
1124-0046  
TTER  
\*1P  
TASK NBR:  
FICHE NBR :  
NOTARIZED: NO  
LPDR: YES

CLASS:

RECP AFFILIATION: NRC

ORG AFFILIATION: CONSOL EDISON OF NY

NG LICENSEE EVENT REPT (RO 50-286/78-006/032L) ON 03/28/78 CONCERNING A  
EILINGERSOLL-RAND, MODEL NO 3X20W, NO 036751 GASKET BETWEEN MECHANICAL  
ND PLATE AND PUMP CASING WAS FOUND TO BE LEAKING AND WAS REPLACED.

124-0047  
TTER  
\*1P  
TASK NBR:  
FICHE NBR :  
NOTARIZED: NO  
LPDR: NO

CLASS:

RECP AFFILIATION: NRC

ORG AFFILIATION: CONSOL EDISON OF NY

NG LICENSEE EVENT REPT (RO 50-286/78-007/03L) ON 03/31/78 CONCERNING  
ORMAL OPERATION, PROCESS RADIATION MONITOR R-11 AND ASSOCIATED MONITOR  
IME INOPERABLE DUE TO A TRIPPED SAMPLE PUMP.

146-0255  
10  
TASK NBR:  
FICHE NBR :  
NOTARIZED: NO  
LPDR: NO

CLASS:

RECP AFFILIATION: NRC

ORG AFFILIATION: NRC

TITLED "EARTHQUAKES, FAULTS, AND NUC PLANTS IN SOUTHERN NEW YORK &  
NEW JERSEY", FOR TRANSMITTAL TO THE BD.