

FEB 14 1973

R. C. DeYoung, Assistant Director for Pressurized Water Reactors,
Directorate of Licensing

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC., INDIAN POINT NUCLEAR
GENERATING UNIT NO. 3, DOCKET NO. 50-286

The enclosure to my memorandum dated December 11, 1972, listed nine unresolved items identified by the L:RS Electrical, Instrumentation and Control Systems Branch. We indicated that there was a possibility that two of the items, "Disconnection of Instrument Buss33" and "Interlocks for Isolation Valves Between Low Pressure and High Pressure Systems", would be resolved by the responses to questions 7.21 and 7.24. We have reviewed the responses to these questions and concluded that the description of the problems and the recommendations for their resolutions contained in my memorandum are still valid. It is requested that the applicant be informed of our positions.

Original Signed by
Donald F. Knuth

ESB-23

Donald F. Knuth, Assistant Director
for Reactor Safety
Directorate of Licensing

cc:

- S. Hanauer, DRFA
- J. Hendrie, L:TR
- A. Giambusso, L:RP
- D. Vassallo, L:PWR 1
- H. Specter, L:PWR 1
- V. Moore, L:EI&CS
- R. Pollard, L:EI&CS
- F. Rosa, L:EI&CS

B111190679 730214
ADDCK 05000286

OFFICE ▶	L:EI&CS	L:EI&CS	L:EI&CS	L:RS		
SURNAME ▶	POLLARD:rl:	ROSA <i>F. R.</i>	MOORE <i>[Signature]</i>	KNUTH <i>[Signature]</i>		<i>Memorandum</i>
DATE ▶	7387 2/14/73	2/14/73	2/14/73	2/14/73		