

TO: B. H. Grier, RO

FS&EB ACTION CONTROL FORM

A. Action Code F0#336

Name of Licensee and Facility Consolidated Edison Co. (Indian Point-3)

Docket No. or License No. 50-286

Title FSAR Meeting Reg. Guide 1.68 Requirements

Origin RO:I

Date Rec'd 3/11/74

B. FS&EB Branch Coordinator:

Bryan \_\_\_\_\_ Dreher X H. D. Thornburg \_\_\_\_\_

Ellis \_\_\_\_\_ Paulus \_\_\_\_\_

C. Action Requested of:

ADREMP \_\_\_\_\_ M&PPOB \_\_\_\_\_ EPB \_\_\_\_\_ RPB \_\_\_\_\_ ADCO X

OB \_\_\_\_\_ CB \_\_\_\_\_ TAB \_\_\_\_\_ OOE \_\_\_\_\_ REGION \_\_\_\_\_

Date Requested 3/13/74 Completion Requested by 4/1/74


Reference RO Inspection Report No. 50-286/74-02 and Memo J. Brunner  
to HD. Thornburg dated 3/6/74.

D. Action Requested: Review referenced data and evaluate as to whether  
specific guidance should be provided on the tests in question.

E. Date Action Completed \_\_\_\_\_

Close-out (Date & Method) \_\_\_\_\_

Comments: If completion date is not consistent with your work  
schedule, please let us know.



*Harold D. Thornburg*  
Harold D. Thornburg, Chief  
Field Support & Enforcement Branch  
Directorate of Regulatory Operations

8111230194 740408  
ADOCK 05000286