



UNITED STATES
ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3942

March 8, 1971

J. B. Henderson, Chief, Reactor Construction
Branch, Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 3
DOCKET NO. 50-286

The enclosed report of the inspection of Consolidated Edison Company's Indian Point No. 3 construction site, performed on January 26 through 28, 1971, by R. F. Heishman and R. L. Brown is forwarded for information.

The investigation of the reactor pressure vessel lifting incident appears to be detailed and thorough with construction progress virtually stopped at the time of the inspection, pending completion of this investigation.

A Construction Deficiency Notice was issued for a lack of documentation attesting to the quality on two steam generators and four accumulators which have been set in place. Documentation relative to the quality of nuclear components supplied by Westinghouse has the potential of becoming a significant problem, since the licensee states that, contractually, documentation is not required and there appears to be a hesitancy to require documentation.

E. M. Howard
E. M. Howard
Senior Reactor Inspector

Enclosure:

CO Rpt. No. 286/71-1, dtd 2/26/71
by R. Heishman and R. Brown

cc: E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL
R. C. DeYoung, DRL
D. J. Skovholt, DRL (3)
A. Giambusso, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
Regional Directors
REG File ✓

8111180076 710308
PDR ADOCK 05000286
G PDR