

UNITED STATES
ATOMIC ENERGY COMMISSION

WASHINGTON, D.C. 20545

JAN 23 1970

R. S. Boyd, Assistant Director for Reactor Projects
Division of Reactor Licensing (2)

CONSOLIDATED EDISON COMPANY (INDIAN POINT UNIT 3) - DOCKET
NO. 50-286/69-10

The enclosed report on the initial quality assurance inspection of
the subject facility is transmitted for information.

As you are aware, Westinghouse, the turnkey contractor for this fa-
cility, is establishing a wholly owned subsidiary, Wedco, to manage
this project. As of the time of the inspection, the owner had not
formally accepted this concept, although the transition was in
progress. We are advised that the licensee plans to submit shortly
a change to the application describing the reorganization.

As described in the report, certain weaknesses in the overall QA pro-
gram were identified. These were discussed with licensee management
in a meeting conducted on January 16, 1970. The results of this
meeting will be reported in CO Report No. 286/70-1.

The inspectors did not find any evidence of deficiencies in the QA
program attributable to the transition of program management from
Westinghouse/UE&C to Wedco, but some information on Wedco's pro-
cedures for implementation of the QA program were not available at
the time of the inspection. This information will be developed during
the continuing inspection program.

J. P. O'Reilly
J. P. O'Reilly, Chief
Reactor Inspection and
Enforcement Branch
Division of Compliance

Enclosure:
CO Rpt No. 286/69-9

cc w/enclosure:

E. G. Case, DRS

S. Levine, DRL (6)

D. J. Skovholt, DRL (3)

L. Kornblith, Jr., CO

R. W. Kirkman, CO:I

J. G. Davis, CO:II

B. H. Grier, CO:III

D. I. Walker, CO:IV

R. W. Smith, CO:V

R. T. Carlson, CO:I

REG Central File

8111180616 700123
PDR ADOCK 05000286
Q PDR