

Enclosure

Description of Noncompliance Item

Consolidated Edison Company

Docket No. 50-286

License No. CPFR-62

The following item appears to be in noncompliance with Appendix B, 10 CFR 50, as identified below:

Criterion XIII, Appendix B, 10 CFR 50 states in part, "When necessary for particular environments . . . temperature levels shall be specified and provided."

Contrary to the above, the heater for the motor drive to containment Spray Pump No. 31 was not connected to a power supply. This item was corrected prior to the end of the inspection.