

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



October 10, 1978
IP-JWK-3152

Docket No. 50-286
License No. DPR-64

Eldon J. Brunner, Chief
Reactor Operations & Nuclear Support Branch
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406


Dear Mr. Brunner:

Your report of Inspection 50-286/78-26, received on September 21, 1978, cited a deficiency for the lack of procedures to define the administration and documentation of training for Maintenance and I & C craft and technician personnel

In response to this violation, procedures have been written which describe the administration of training required for the Maintenance and I & C Departments' craft and technician personnel and methods for the documentation of training completed. These procedures are currently being reviewed by appropriate department personnel and will be issued by October 31, 1978.

It is our opinion that the actions described above are adequate to correct and to avoid recurrence of this item of non-compliance.

Very truly yours,



J. P. Bayne
Resident Manager

JWK/rbb

cc: G. T. Berry
G. M. Wilverding
P. W. Lyon
J. F. Davis

7811080086