

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

June 24, 1977

Indian Point Station
Docket Nos. 50-247
50-286


Mr. Eldon J. Brunner, Chief
Reactor Operations and Nuclear Support Branch
U. S. Nuclear Regulatory Commission, Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Brunner

This refers to Inspection Nos. 50-247/77-12 and 50-286/77-13, conducted by your Messrs. J. Streeter and J. Kottan on April 24 - 28, May 5, and May 9 - 13, 1977 of activities authorized by NRC License Nos. DPR-26 and DPR-64 at our Indian Point Station. Your June 3, 1977 letter indicated that one of our activities was not conducted in full compliance with NRC requirements. This particular activity was set forth in the Notice of Violation enclosed as Appendix A to your letter. Our response to this item of apparent non-compliance is as follows:

The following action will prevent future delays in completing corrective measures for similar items. These items, as they are established, will be factored into our computerized Licensing and Regulatory Status Report. As an adjunct to this system, the status summary report that is routinely produced and distributed to appropriate personnel, will aid in the timely completion of all future identified tasks and commitments.

Very truly yours



8110310532 770712
PDR ADOCK 05000247
Q PDR