

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

August 26, 1977

Indian Point Station
Docket Nos. 50-247
50-286

Mr. Eldon J. Brunner, Chief
Reactor Operations and Nuclear Support Branch
U.S. Nuclear Regulatory Commission, Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Brunner

This refers to Inspection Nos. 50-247/77-21 and 50-286/77-21 conducted by Mr. J. Streeter, Reactor Inspector, on June 14 - 17, 21 - 24, 1977, of activities authorized by NRC License Nos. DPR-26 and DPR-64 at our Indian Point Station. Your August 4, 1977, letter indicated that one of our activities was not conducted in full compliance with NRC requirements. This activity was set forth in the Notice of Violation enclosed as Appendix A to your letter. Our response to this item is as follows:

Notations documenting the installation of the subject jumpers have been added to the Watch Supervisor's log book. To prevent recurrence of this item, the appropriate responsible personnel have been cautioned to strictly adhere to the requirements of Station Administrative Order No. 126 regarding recording of jumper installations in the Watch Supervisor's log.

Very truly yours



8110310560 770907
PDR ADOCK 05000247
G PDR