

OCT 3 1974

Note to H. D. Thornburg

RO INSPECTION RPT. NO. 50-286/74-16 (IPS-3, CEC)

As requested by AICF # H00258H1, we have reviewed the subject report and have the following comments:

- 1. TI-4000/2, Section I, page I-2, paragraph 3, details appropriate action to be taken based upon the inspection findings.
- 2. TI-4000/2, Section I, page I-4, paragraph 6, discusses the applicability of references and guidance.
- 3. The proposed inspection should be conducted in accordance with TI-4000/2. If specific significant deficiencies are found, the details should be forwarded to RO:HQ for resolution.

Original signed by
J.H. Sniezek

J. H. Sniezek, RO

cc:

EJBrunner, RO:I
RO Files

8111050791	741003
PDR ADOCK	05000286
Q	PDR

OFFICE >	RO:FIB:AC					
SURNAME >	JHSniezek					
DATE >	7451/mt					
	10/3/74					