

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

7 8

REPORT SOURCE

L	6	0	5	0	0	0	2	4	7	7	0	6	2	1	8	0	8	0	7	1	7	8	0	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 68 69 74 75 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 | _____ 80

SYSTEM CODE H H (11)		CAUSE CODE A (12)	CAUSE SUBCODE F (13)	COMPONENT CODE C K T B R K (14)				COMP. SUBCODE E (15)	VALVE SUBCODE Z (16)
0 9 (7 8)									
LER/RO REPORT NUMBER (17)	EVENT YEAR 8 0 (21 22)		SEQUENTIAL REPORT NO. 0 0 7 (24 26)		OCCURRENCE CODE 0 3 (28 29)	REPORT TYPE L (30)		REVISION NO. 0 (32)	
ACTION TAKEN H (18)	FUTURE ACTION Z (19)	EFFECT ON PLANT Z (20)	SHUTDOWN METHOD Z (21)	HOURS 0 0 0 0 (22 40)	ATTACHMENT SUBMITTED N (23)	NPRD-4 FORM SUB. N (24)	PRIME COMP. SUPPLIER N (25)	COMPONENT MANUFACTURER W 1 2 0 (26 47)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event is believed to have been caused by the unauthorized
1 1 actuation of the pumps transfer switch by a security watch person.
1 2 All security personnel were reinstructed in this matter. The subject
1 3 watch person was dismissed from the site and the Shift Security Super-
1 4 visor was suspended from his position.

FACILITY STATUS: 1 5 E (28)
 % POWER: 1 0 0 (29)
 OTHER STATUS: NA (30)
 METHOD OF DISCOVERY: A (31)
 DISCOVERY DESCRIPTION: Control Room Instrumentation (32)

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA	(39)			

PERSONNEL INJURIES					
NUMBER			DESCRIPTION		
1	8		0	0	0
			(40)	NA	

		LOSS OF OR DAMAGE TO FACILITY		
		TYPE	DESCRIPTION	
1	9	Z(42)	NA	(43)

ISSUED		DESCRIPTION		PUBLICITY			
2	0	N	(44)	NA	(45)		

NRC USE ONLY

NRC USE ONLY

8007240172

NAME OF PREPARER

John M. Makepeace

PHONE:

914-737-8823

5 PO 917-926