

John D. O'Toole  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003  
Telephone (212) 460-2533

August 6, 1982

Re: Indian Point Unit No. 2  
Docket No. 50-247

Director of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief  
Operating Reactors Branch #1  
Division of Licensing


Dear Mr. Varga:

This is in response to your June 30, 1982 letter which requested our schedule for responding to the information request attached thereto. By letter dated July 1, 1982 we indicated that due to additional required modifications our best estimate for completion of NUREG-0737 Item II.B.3 is prior to returning the unit to service from the upcoming Fall 1982 refueling/maintenance outage. Accordingly, final design details regarding our implementation of this Task Item will be provided for your post-implementation review by March 1, 1983.

A review of our on-going program to implement Task Item II.B.3 with regard to the "clarifications" appearing in the Attachment to your June 30, 1982 letter has revealed a difference concerning accuracy requirements (criterion 10 clarification). The reason for this is that we have proceeded with implementation of this Task Item based on existing NUREG- 0737 criteria established prior to the issuance of these new clarifying criteria. We take exception to the imposition of these new requirements at this time and will provide with our March 1, 1983 response the accuracy of the instrumentation which we have already procured to meet the requirements for post-accident monitoring capability.

Should you or your staff have any questions, please contact us.

Very truly yours,



A046

8208160012 820806  
PDR ADOCK 05000247  
P PDR