

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

April 9, 1985

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Dear Mr. Varga:

By letter dated February 4, 1985 we provided our response to your request for additional information regarding Auxiliary Feedwater System (AFWS) seismic qualification at Indian Point Unit No. 2. In Attachment 1 Section 5(c) of that response we indicated a support modification was required to seismically restrain the overhead space heaters. While preparing to implement the above modification a re-evaluation was performed, indicating that the space heaters, with their present location and support configuration, will not affect the required safety function of the AFWS during a Safe Shutdown Earthquake (SSE). Therefore, the space heaters do not require a modification.

Should you or your staff have any additional questions, please contact us.

Very truly yours,



cc: Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

8504150284 850409
PDR ADDCK 05000247
P PDR

A001
1/0