

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

June 10, 1986

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Ms. Marylee Slosson, Project Manager
PWR Project Directorate No. 3
Division of PWR Licensing - A

Dear Ms. Slosson:

This is in response to your recent telephone request to verify in writing the staff requirements as stated in the March 28, 1984 letter transmitting a Safety Evaluation Report (SER) concluding that the reactor coolant system for Indian Point Unit No. 2 could withstand the effects of asymmetric LOCA loads. After receipt of the March 28, 1984 SER it was our understanding based on discussion with the NRC staff that no written confirmation was required. Specifically, the SER requested verification of the shield plug assumptions, determination of the effects of the plugs as missiles, and determination that structural components do not inhibit plug displacement. We have verified that these matters were satisfactorily completed after receipt of the March 28, 1984 SER.

Should you have any questions, please contact us.

Very truly yours,



cc: Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

8606170137 860610
PDR ADOCK 05000247
P PDR

A001
1/0