

Murray Selman  
Vice President

Consolidated Edison Company of New York, Inc.  
Indian Point Station  
Broadway & Bleakley Avenue  
Buchanan, NY 10511  
Telephone (914) 737-8116

August 21, 1986

Re: Indian Point Unit No. 2  
Docket No. 50-247

Director of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

ATTN: Mr. Steven A. Varga, Project Director  
PWR Project Directorate No. 3  
Division of PWR Licensing - A

Dear Mr. Varga:

Inservice examinations and tests of the Indian Point Unit No. 2 Reactor Vessel, and primary and secondary side components and piping were performed during the recently completed seventh refueling outage. These examinations and tests begin the first period of the Second 10-Year Inservice Inspection Interval. The examinations and tests were conducted to satisfy the requirements of Section 4.2 of the Technical Specifications and the Consolidated Edison Inservice Inspection and Testing Program.

A report of the work performed, and the areas subject to examination and test are provided in Attachments A and B to this letter.

The detailed data are presently being compiled and will be available at the plant site for review by your staff when completed.

Very truly yours,



attach.

cc: Senior Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, New York 10511

8608260268 860821  
PDR ADOCK 05000247  
Q PDR

A047  
11