



Sterling Diagnostics, Inc

36645 Metro Court

Sterling Heights, Michigan 48312 U.S.A.

Tel. Nos.: (586) 979-2141

(800) 637-2661

Fax: (586) 979-4971

Email: info@sterlingdiagnostics.com

Website: sterlingdiagnostics.com

January 29, 2010

U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road, Suite 210
Lisle, Illinois 60532-4351

Attention: Robert P. Hays

Dear Sirs:

In reference to our by product material license (license no. 21-26030-01), we hereby request that the license be amended to replace **Radiation Safety Officer, David Callender** with **Noli Cruz, as our new Radiation Safety Officer** effective immediately.

Sincerely yours,

LUZ STA. MARIA
Office Manager

RECEIVED FEB 02 2010

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Sterling Diagnostics, Inc. 36645 Metro Court Sterling Heights, MI 48310		2. NRC/REGIONAL OFFICE: U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
3. DOCKET NUMBER(S) 030-31055		4. LICENSEE NUMBER(S) 21-26030-01	
5. DATE(S) OF INSPECTION January 21, 2010			

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

inspector as non-cited violations, are not being cited because they were self-being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-

discussed involving the following requirement(s) and Corrective Action(s):



UNITED STATES NUCLEAR REGULATORY COMMISSION

Robert P. Hays
Health Physicist
DNMS/MIB/RIII

Region III
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

Telephone: (630) 829-9819
Fax: (630) 829-9782
E-mail: robert.hays@nrc.gov

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

License Condition 11.B. Radiation Safety Officer.
Contrary to License Condition 11.B., the Radiation Safety Officer, David Callender, was no longer working as the Radiation Safety Officer and the license has not been amended to indicate a replacement Radiation Safety Officer

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	LUZ STA. MARIA	<i>[Signature]</i>	01/21/2010
NRC INSPECTOR	Robert P. Hays	<i>[Signature]</i>	1/21/2010



Sterling Diagnostics, Inc.

36645 Metro Court

Sterling Heights, Michigan 48312 U.S.A



02 1P

\$ 000.44⁰

0003973752 **JAN 29 2010**

MAILED FROM ZIP CODE 48312

U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4351

605324352

