

Murray Selman
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

November 25, 1987

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Report of Reactor Vessel Special Inspection

Pursuant to the provisions of the Indian Point Unit No. 2 Technical Specifications, Section 4.2.G, Item 7.2, attached for your review and approval is a report, entitled "Indian Point Unit 2 Reactor Vessel Special Inspection", which describes special inspections performed on the Indian Point Unit 2 reactor vessel during the current outage.

The inspections utilized a variety of examination techniques including state-of-the-art ultrasonic techniques and an up-to-date data processing system as discussed with the NRC staff in several meetings and telephone conversations in the past three years. Additionally, the field examinations have generally been conducted in accordance with our inspection program submitted on April 21, 1987. The number of data points obtained were numerous. Accordingly, we would be happy to meet with you and your staff to discuss these inspections if you wish.

Very truly yours,

Murray Selman

cc: Ms. Marylee M. Slosson
Project Directorate I-1
Division of Reactor Projects I/II
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. William Russell
Regional Administrator - Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, NY 10511

8712030252 871125
PDR ADDCK 05000247
Q PDR

AP47
11