Consolidated Edison Company of New York, Inc. Indian Point Station
Broadway & Bleakley Avenue
Buchanan. NY 10511
Telephone (914) 737-8116

June 15, 1989

Re:

Indian Point Unit No. 2 Docket No. 50-247

Document Control Desk US Nuclear Regulatory Commission Mail Station P1-137 Washington, DC 20555

SUBJECT: Emergency Action Levels

This is to clarify our June 13, 1989 letter regarding the same subject. Our review will address NUREG-0654 and events in Revision 4 of our Emergency Action Levels. Nevertheless, the NUREG-0654 Appendix 1 examples cited by your inspector (which were listed in our previous letter) will be fully covered in the revisions which will result from our review. As noted in our June 9, 1989 exit interview following the recent inspection, as well as in your January 31, 1989 letter, literal adherence to the guidance in NUREG-0654 is not required.

This review and revision, together with all associated training, will be completed within 60 days of the date of this letter.

Very truly yours,

cc: Mr. William Russell
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1498

Mr. Donald S. Brinkman, Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector US Nuclear Regulatory Commission PO Box 38 Buchanan, NY 10511

8906270449 890615 PDR ADOCK 05000247 P PNU JE35