

Stephen B. Bram
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

December 13, 1991

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555


SUBJECT: Steam Generator Tube Inservice Inspection Program
Results

The results of steam generator tube inspections as conducted at Indian Point Unit No. 2 (IP-2) during the 1991 refueling outage were submitted by a Con Edison letter dated July 26, 1991.

Based upon the results of this recent inspection, we have concluded that the next steam generator tube examination should be conducted during the next refueling outage in 1993. In accordance with Technical Specification 4.13.C.5 we request that you approve continued plant operation until commencement of the 1993 refueling outage.

Should you have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,



cc: Mr. Thomas T. Martin
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Francis J. Williams, Jr., Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

270 9201030038 911213
PDR ADOCK 05000247
P PDR

AD47 1/0