


February 1, 2010

MEMORANDUM TO: File

FROM: Robert P. Hays, Health Physicist,   
Materials Inspection Branch  
Division of Nuclear Materials Safety

SUBJECT: FAIRVIEW RADIOLOGY, 030-32143, 21-26306-01  
Inspection Record No. 2010-01; AITS No. M10-0003

On January 22, 2010, two inspectors attempted to perform an inspection of the subject licensee at the authorized location of use, 5245 Schafer Road, Suite A, Dearborn, Michigan to verify that licensed activities had ceased as per the Order. The inspection determined that the licensee had moved out from Suite A and was currently occupied by a Physical Therapy Group, Advance Rehabilitation Clinic. The inspectors queried the current occupant, Michael Daneshvar, R.P.T., about the former occupant, Fairview Radiology, specifically, Frank Fayz, M.D. Mr. Daneshvar informed the inspectors that he was the building owner and landlord for Dr. Fayz and that Dr. Fayz had moved out in December 2009. Mr. Daneshvar also informed the inspectors that an individual, presumably a physicist for Dr. Fayz, had come by during December 2009, and did surveys and wipe tests of the hot lab and all property belonging to Dr. Fayz had been removed from the premises. Mr. Daneshvar allowed the inspectors a walk-through of the facility to verify that no property or licensed materials remained in the authorized location of use. Ambient surveys of the hot lab indicated only background radiation levels. The inspectors also learned that Dr. Fayz had relocated his office to 22000 Ford Road, Dearborn Heights, Michigan, with no change in telephone no. 313-581-3000. The inspectors traveled to 22000 Ford Road and determined that Dr. Fayz was not available at the time the inspectors arrived, however, a secretary for Dr. Fayz was available. A walk-through of Dr. Fayz's second floor office space indicated that this location was mainly a storage facility for patient records and office equipment. No nuclear medicine medical equipment or a scanning room was observed. It was verified with the secretary that no patient scans were performed at that facility. The inspectors left a contact telephone number with the secretary and requested that Dr. Fayz contact the inspectors to follow up with the inspection and to determine where the remaining licensed material was transferred. Dr. Fayz subsequently contacted one of the inspectors and informed him that all licensed material had been transferred to the physicist and the physicist had mailed to the Regional office a termination request, licensed material transfer information, and closeout surveys of the hot lab at 5245 Schaefer Road, Dearborn, Michigan. Follow up at the office for the submitted documentation determined that the amendment request had been received on January 22, 2010, with Control No. 318775, and Accession No. ML100220895. AITS No. M10-0003 should now be considered closed.

**DIVISION OF NUCLEAR MATERIAL AND SAFETY  
ACTION ITEM TRACKING SYSTEM (AITS)  
CONTROL REPORT**

AITS NUMBER: M10-0003

DATE INITIALED: 11/30/2009

INCOMING REQUESTOR/REQUESTED BY: REYNOLDS

PUBLIC RESPONSIVENESS: YES \_\_\_ NO X

DESCRIPTION: ORDER REVOKING LICENSE WITHIN 30 DAYS BASED ON NONPAYMENT OF LICENSE FEES - FAIRVIEW RADIOLOGY

REMARKS/SPECIAL INSTRUCTIONS:

Edl

313 581 3000

ASSIGNED TO/DIVISION: BLOOMER

ADDITIONAL ASSIGNEES:

DATE DUE: 11/20/2009

CLOSEOUT ACTION:

Inspection on January 22, 2010

DATE CLOSED:

February 1, 2010. memo to file  
as attached.