

APPENDIX A

Notice of Violation

Consolidated Edison Company of New York, Inc.
Indian Point Unit 2

Docket No. 50-247
License No. DPR-26

During an NRC inspection conducted from June 14, 1992 to July 25, 1992 a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1991), the violation is listed below:

Technical Specification 3.13.D, Fire Detection Systems, requires that two smoke detectors be operable for each reactor coolant pump (RCP). If this requirement cannot be met, containment air temperature must be monitored at least once per hour or a fire watch established once per eight hours.

Contrary to the above, from May 5 to May 7, while only one 22 RCP smoke detector was operable, containment air temperature was not monitored at least once per hour nor a fire watch established once per eight hours.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Consolidated Edison Company of New York, Inc., is hereby required to submit to this office within 30 days of the date of this letter which transmitted this notice a written statement of explanation in reply. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include: (1) the reason for the violation, or, if contested, the basis for disputing the violation; (2) the corrective action steps which have been taken and the results achieved; (3) corrective actions steps which will be taken to avoid further violations; and, (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.