

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



December 17, 1980
IP-FWG-11157

Docket No. 50-286
License No. DPR-64

Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Report LER 80-016/01T-0 is hereby submitted in accordance with the requirements of I. E. Bulletin 80-24, Prevention of Damage due to Water Leakage Inside Containment, Section 2.f. Three copies of this letter and attachment are enclosed as required. This constitutes the fourteen day report required by I. E. Bulletin 80-24 and accompanies the twenty-four hour notification of December 5, 1980.

Very truly yours,

S. S. Zulla
S. S. Zulla
Resident Manager

FWG/bam

cc: Director of Nuclear Reactor Regulation
Attn: William McDonald, Director (3 Copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Office of Inspection and Enforcement (30 Copies)
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

Resident Inspector T. Rebelowski
George Wilverding, NYO
J. P. Bayne, NYO
James Davis (SRC), NYO

Nuclear Safety Analysis Center
Electric Power Research Institute
P. O. Box 10412
Palo Alto, California 94303

8012290425

A002

5
11/11
DEC 29 AM 9 44
DISTRIBUTION SERVICES UNIT

DISTRIBUTION SERVICES UNIT