Stephen E. Quinn Vice President

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, NY 10511 Telephone (914) 734-5340

November 18, 1996

Re:

Indian Point Unit No. 2 Docket No. 50-247

Document Control Desk US Nuclear Regulatory Commission Mail Station P1-137 Washington, DC 20555

SUBJECT: Response to NRC Generic Letter 96-06

Members of the regulatory staff have requested clarification of our response provided on October 30, 1996 to the referenced generic letter. In our response we referred to "preliminary" analysis that had been completed for Fan Cooler Unit fluid heat up which showed no boiling during the first 25 seconds post accident. We also indicated that additional analyses were being performed. The conclusions drawn in the October 30, 1996 response were based upon the "preliminary" analysis described in the submittal, and were therefore also preliminary. The additional analyses being performed cover all areas needed to respond to the Generic Letter including the Fan Cooler Unit fluid heat up calculations. Our inquiry into these matters is continuing, and our response to the generic letter will be submitted within the requested 120 day response period.

Should there be further questions in this regard, please contact Charles W. Jackson, Manager Nuclear Safety & Licensing.

Very truly yours,

Super . Our

Subscribed and sworn to before me this 16 day of November, 1996.

WANUEL SANCHEZ, JR.
Wotary Public, State of New York
No. 3443310

Qualified in Durchess County

CommissivetaryiPablioch 30, 19

A07210

cc: Mr. Hubert J. Miller
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector US Nuclear Regulatory Commission PO Box 38 Buchanan, NY 10511