

Stephen E. Quinn  
Vice President

Consolidated Edison Company of New York, Inc.  
Indian Point Station  
Broadway & Bleakley Avenue  
Buchanan, NY 10511  
Telephone (914) 734-5340

April 17, 1997

Re: Indian Point Unit No. 2  
Docket No. 50-247

Document Control Desk  
US Nuclear Regulatory Commission  
Mail Station P1-137  
Washington, DC 20555


SUBJECT: On-Line Calibration and Extended Deviation Limits for Rod  
Position Indicators - Indian Point 2 Cycle 14

Attached please find the results of the calculations performed for the captioned subject. The results are for the Indian Point 2 Cycle 14 design and include a comparison with previous cycles. These results were discussed at a meeting between Con Edison and the NRC on March 31, 1997.

The information is proprietary to Con Edison and the appropriate affidavit is also enclosed.

Should you have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,



Enclosed

C: Mr. Hubert J. Miller  
Regional Administrator - Region I  
US Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager  
Project Directorate I-1  
Division of Reactor Projects I/II  
US Nuclear Regulatory Commission  
Mail Stop 14B-2  
Washington, DC 20555

Senior Resident Inspector  
US Nuclear Regulatory Commission  
PO Box 38  
Buchanan, NY 10511

Margaret Chatterton

240000  
9704250014 970417  
PDR ADOCK 05000247  
P PDR



PROP

ENCLOSURE 1

PROPRIETARY AFFIDAVIT

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.  
INDIAN POINT UNIT NO. 2  
DOCKET NO. 50-247  
APRIL, 1997