

Paul H. Kinkel  
Vice President

Consolidated Edison Company of New York, Inc.  
Indian Point Station  
Broadway & Bleakley Avenue  
Buchanan, NY 10511  
Telephone (914) 734-5340  
Fax: (914) 734-5923

October 8, 1997

Re: Indian Point Unit No. 2

Docket No. 50-247

Mr. Hubert J. Miller  
Regional Administrator - Region I  
US Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

SUBJECT: Required Notification in Accordance with 10 CFR 50.9

Dear Mr. Miller:

The purpose of this letter is to document notification made by our Test and Performance Manager to the Senior Resident Inspector - Indian Point 2 on August 25, 1997, of our preliminary determination that certain records associated with routine surveillance tests performed on emergency lighting installed pursuant to 10 CFR 50 Appendix R may be inaccurate. Specifically, we believed that certain steps in the test procedure may have been signed as completed when in fact they may have been incomplete or conducted in a manner not fully consistent with the test procedure. Our investigation, which substantiated our preliminary determination, was concluded on October 7, 1997. Results of the investigation and our actions will be provided to the Senior Resident Inspector.

Should you have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,

*Paul H. Kinkel*

IEDI/0

9710170073 971008  
PDR ADOCK 05000247  
PDR



C: Document Control Desk  
US Nuclear Regulatory Commission  
Mail Station P1-137  
Washington, DC 20555

Mr. Jefferey F. Harold, Project Manager  
Project Directorate I-1  
Division of Reactor Projects I/II  
US Nuclear Regulatory Commission  
Mail Stop 14B-2  
Washington, DC 20555

Senior Resident Inspector  
US Nuclear Regulatory Commission  
PO Box 38  
Buchanan, NY 10511