

Paul H. Kinkel
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5923

April 15, 1998

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

Subject: Generic Letter 93-04, "Rod Control System Failure and Withdrawal
of Rod Control Cluster Assemblies"

Reference: Letter Paul H. Kinkel, Con Edison, to Document Control Desk,
Dated December 11, 1997

As requested, this letter supplements the above referenced letter to note that Con Edison's Salem Rod Withdrawal Modification, conducted in accordance with Generic Letter 93-04, was completed during our 1997 refueling outage which ended July 11, 1997. In addition, the current order surveillance test, recommended by the Westinghouse Owners Group, has also been implemented.

Should you have any questions please contact Mr. Charles W. Jackson, manager,
Nuclear Safety and Licensing.

Very truly yours,

Paul H. Kinkel

AO301/0

9804220351 980415
PDR ADDCK 05000247
P PDR

cc: Mr. Hubert J. Miller
Regional Administrator-Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511