

Paul H. Kinkel
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5923

March 20, 1998

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

Reference: Licensee Event Report 97-04, April 4, 1997

One of the corrective actions contained in the above referenced report, stated that "this LER will be reviewed in the next session of Continuing Training for Engineering Support Personnel, with a currently scheduled completion date of 12/31/97". Due to an unplanned and continuing outage at Indian Point Unit No. 2, not all Engineering Support personnel were able to receive the training by December 31, 1997. The topics discussed in LER 97-04 will be reviewed by Engineering Support personnel as part of the next session of training which is presently scheduled for completion by July 1, 1998.

Should you have any questions please contact Mr. Charles W. Jackson at (914) 734-5127.

Very truly yours,

Paul H. Kinkel

cc: Mr. Hubert J. Miller
Regional Administrator-Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Jessie

9804020235 980320
PDR ADOCK 05000247
S PDR

Mr. Jefferey F. Harold, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511