

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 2443 WARRENVILLE ROAD, SUITE 210 LISLE, IL 60532-4352

February 12, 2010

EA-06-178

Mr. Larry Meyer Site Vice-President NextEra Energy Point Beach, LLC 6610 Nuclear Road Two Rivers, WI 54241

SUBJECT: ERRATA TO POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2,

NRC INTEGRATED INSPECTION REPORT 05000266/2009005;

05000301/2009005 AND STATUS OF CONFIRMATORY ORDER EA-06-178

Dear Mr. Meyer:

On February 10, 2010, the U.S. Nuclear Regulatory Commission (NRC) issued Integrated Inspection Report 05000266/2009005 and 05000301/2009005 (ML100410106) for your Point Beach Nuclear Plant, Units 1 and 2. Inspection report sections documenting the completion of a performance indicator verification for Units 1 and 2, and the completion of quarterly resident inspector observations of security personnel and activities, were inadvertently omitted from the original report. The enclosed errata contains the omitted sections and should be inserted as pages 41(a) and 52(a) into Integrated Inspection Report 05000266/2009005; 05000301/2009005.

Sincerely,

/RA/

Michael A. Kunowski, Chief Branch 5 Division of Reactor Projects

Docket Nos. 50-266; 50-301 License Nos. DPR-24; DPR-27

Enclosure: Errata to Inspection Report No. 05000266/2009005; 05000301/2009005

cc w/encl: Distribution via ListServe

Errata to NRC Integrated Inspection Report 05000266/2009005 and 05000301/2009005

In Inspection Report 05000266/2009005 and 05000301/2009005, insert the following as pages 41(a) under Section 4OA1, and 52(a) under Section 4OA5:

4OA1 PI Verification (71151)

.8 Safety System Functional Failures

a. Inspection Scope

The inspectors sampled licensee submittals for the Safety System Functional Failures PI for Unit 1 and Unit 2 for the third quarter 2008 through third quarter 2009. To determine the accuracy of the PI data, PI definitions and guidance contained in NEI 99-02, Revision 5, and NUREG-1022, "Event Reporting Guidelines 10 CFR 50.72 and 50.73," were used. The inspectors reviewed the licensee's operator narrative logs, operability assessments, maintenance rule records, maintenance work orders, issue reports, event reports and NRC Integrated IRs to validate the accuracy of the submittals. The inspectors also reviewed the licensee's issue report database to determine if any problems had been identified with the PI data collected or transmitted for this indicator and none were identified. Documents reviewed are listed in the Attachment to this report.

This inspection constituted two safety system functional failures samples as defined in IP 71151-05.

b. Findings

No findings of significance were identified.

41(a) Enclosure

4OA5 Other Activities

.6 Quarterly Resident Inspector Observations of Security Personnel and Activities

a. Inspection Scope

During the inspection period, the inspectors conducted observations of security force personnel and activities to ensure that the activities were consistent with licensee security procedures and regulatory requirements relating to nuclear plant security. These observations took place during both normal and off-normal plant working hours.

These quarterly resident inspector observations of security force personnel and activities did not constitute any additional inspection samples. Rather, they were considered an integral part of the inspectors' normal plant status review and inspection activities.

b. Findings

No findings of significance were identified.

52(a) Enclosure



UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 2443 WARRENVILLE ROAD, SUITE 210 LISLE, IL 60532-4352

February 12, 2010

EA-06-178

Mr. Larry Meyer Site Vice-President NextEra Energy Point Beach, LLC 6610 Nuclear Road Two Rivers, WI 54241

SUBJECT: ERRATA TO POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2,

NRC INTEGRATED INSPECTION REPORT 05000266/2009005:

05000301/2009005 AND STATUS OF CONFIRMATORY ORDER EA-06-178

Dear Mr. Meyer:

On February 10, 2010, the U.S. Nuclear Regulatory Commission (NRC) issued Integrated Inspection Report 05000266/2009005 and 05000301/2009005 (ML100410106) for your Point Beach Nuclear Plant, Units 1 and 2. Inspection report sections documenting the completion of a performance indicator verification for Units 1 and 2, and the completion of quarterly resident inspector observations of security personnel and activities, were inadvertently omitted from the original report. The enclosed errata contains the omitted sections and should be inserted as pages 41(a) and 52(a) into Integrated Inspection Report 05000266/2009005; 05000301/2009005.

Sincerely,

Michael A. Kunowski, Chief /RA/ Branch 5 Division of Reactor Projects

Docket Nos. 50-266; 50-301 License Nos. DPR-24; DPR-27

Enclosure: Errata to Inspection Report No. 05000266/2009005; 05000301/2009005

cc w/encl: Distribution via ListServe

DOCUMENT NAME: G:\1-SECY\1-WORK IN PROGRESS\POI 2009 005 ERRATA.DOC

□ Publicly Available □ Non-Publicly Available □ Sensitive □ Non-Sensitive <u>See previous concurrences</u>

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl

"E" = Copy with attach/encl "N" = No copy

OFFICE	RIII		RIII		RIII	RIII	
NAME	RKrsek:cms		MKunowski				
DATE	02/11/2010		02/12/2010				

OFFICIAL RECORD COPY

Letter to L. Meyer from M. Kunowski dated February 12, 2010

SUBJECT: ERRATA TO POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2,

NRC INTEGRATED INSPECTION REPORT 05000266/2009005;

05000301/2009005 AND STATUS OF CONFIRMATORY ORDER EA-06-178

DISTRIBUTION:

Susan Bagley

RidsNrrDorlLpl3-1 Resource

RidsNrrPMPointBeach

RidsNrrDirsIrib Resource

Cynthia Pederson

Steven Orth

Jared Heck

Allan Barker

Carole Ariano

Linda Linn

DRPIII

DRSIII

Patricia Buckley

Tammy Tomczak

ROPreports Resource