

UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

March 7, 1994

Docket No. 50-286

Mr. William A. Josiger, Acting Executive Vice President - Nuclear Generation Power Authority of the State of New York 123 Main Street White Plains, New York 10601

Dear Mr. Josiger:

SUBJECT: ENVIRONMENTAL ASSESSMENT AND FINDING OF NO SIGNIFICANT IMPACT -EXEMPTION FROM THE REQUIREMENTS OF 10 CFR PART 50, APPENDIX R, SECTION III.G.2, FOR THE INDIAN POINT NUCLEAR GENERATING UNIT NO. 3 (TAC NO. M88323)

Enclosed is a copy of an "Environmental Assessment and Finding of No Significant Impact" for your information. This assessment relates to the Power Authority of the State of New York's (PASNY's) application dated November 30, 1993, in which PASNY requested an exemption from the requirements of 10 CFR Part 50, Appendix R, Section III.G.2, which specifies requirements to ensure that one train of redundant equipment necessary to achieve and maintain hot shutdown remains free of fire damage.

During a programmatic review of Fire Protection Program and Appendix R compliance strategy at Indian Point Nuclear Generating Unit No. 3, PASNY identified that certain safe shutdown instrument sensing lines inside containment do not meet the separation requirements of Section III.G.2 of 10 CFR Part 50, Appendix R. Specifically, in some areas the wide-range steam generator water level and pressurizer level sensing lines are not separated by a horizontal distance of 20 feet, nor are they separated by a radiant energy shield. In addition, fire detection and suppression in the area is limited. The request for exemption from the requirements of 10 CFR Part 50, Appendix R, Section III.G.2, was limited to these sensing lines.

PASNY based its request for exemption on a determination that the low combustible loadings within containment, combined with the sensing lines' physical configurations and installation characteristics, ensure that at least one train of safe shutdown instrumentation will remain capable of performing its intended function during and after a postulated fire.

003780193

NRC FILE CENTER

cr.3

090008

403100038 940307

ADOCK 05000286

This notice has been forwarded to the Office of the Federal Register for publication.

Sincerely,

H. Z. Comme

Nicola F. Conicella, Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Enclosure: Environmental Assessment

cc w/enclosure: See next page Mr. William A. Josiger Power Authority of the State of New York

cc:

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406

Mr. Gerald C. Goldstein Assistant General Counsel Power Authority of the State of New York 1633 Broadway New York, New York 10019

Mr. S. David Freeman, President and Chief Executive Officer Power Authority of the State of New York 123 Main Street White Plains, New York 10601

Mr. John H. Garrity Resident Manager Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511

Mr. Peter Kokolakis Director Nuclear Licensing - PWR Power Authority of the State of New York 123 Main Street White Plains, New York 10601

Ms. Donna Ross New York State Energy Office 2 Empire State Plaza 16th Floor Albany, New York 12223

Charles Donaldson, Esquire Assistant Attorney General New York Department of Law 120 Broadway New York, New York 10271 Indian Point Nuclear Generating Station Unit No. 3

Resident Inspector Indian Point 3 Nuclear Power Plant U.S. Nuclear Regulatory Commission P.O. Box 337 Buchanan, New York 10511

Mr. Charles W. Jackson Manager, Nuclear Safety and Licensing Consolidated Edison Company of New York, Inc. Broadway and Bleakley Avenues Buchanan, New York 10511

Mayor, Village of Buchanan 236 Tate Avenue Buchanan, New York 10511

Mr. Leslie M. Hill Vice President - Appraisal and Compliance Services Power Authority of the State of New York 123 Main Street White Plains, New York 10601

Union of Concerned Scientists Attn: Mr. Robert D. Pollard 1616 P Street, NW, Suite 310 Washington, DC 20036