

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



L. M. Hill
Site Executive Officer

December 1, 1995
IPN-95-123

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
Licensee Event Report # 95-017-01
**Failure to Implement Technical Specification Required Surveillance for
an Inoperable Level Channel on the 34 Safety Injection Accumulator;
A Condition Prohibited By Technical Specifications**

Dear Sir:

The attached Licensee Event Report (LER) 95-017-01 is hereby submitted as required by 10 CFR 50.73. This event is the type defined in 10 CFR 50.73 (a)(2)(i)(B). This supplement provides the additional corrective actions committed in letter IPN-95-097 dated September 22, 1995.

Also attached are the commitments made by the Authority in this letter.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'L. Hill'.

L. M. Hill
Site Executive Officer
Indian Point 3 Nuclear Power Plant

LMH/vjw

Attachments
cc: See next page

110047

9512110093 951201
PDR ADOCK 05000286
S PDR

LE22
11

cc: Mr. Thomas T. Martin
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant

List of Commitments

Number	Commitment	Due
IPN-95-123-01	Operations will review the process and documentation which support the accurate completion of instrument channel checks required by Instrument & Control technical and operational specifications.	February 14, 1996
IPN-95-123-02	Operations will revise procedure(s), as required, to incorporate the changes identified by the review of the process and documentation which support the accurate completion of instrument channel checks.	April 18, 1996.