

**Indian Point 3
Nuclear Power Plant**
P.O. Box 215
Buchanan, New York 10511
914-736-8000



March 14, 1996
IPN-96-028

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
Monthly Operating Report for February 1996

Dear Sir:

The attached monthly operating report, for the month of February 1996, is hereby submitted in accordance with Indian Point 3 Nuclear Power Plant Technical Specification 6.9.1.4.

The Authority is making no commitments in this letter.

Very truly yours,


R. J. Barrett
Plant Manager
Indian Point 3 Nuclear Power Plant

LMH/cl

Attachment

cc: See next page

9603210189 960229
PDR ADOCK 05000286
R PDR

IEDA
||

cc: Thomas T. Martin
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant

John J. McOscar, Director
Division of Resource Management and Administration
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Records Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

OPERATING DATA REPORT

DOCKET NO. 50-286
 DATE 03-5-96
 COMPLETED BY T. Orlando
 TELEPHONE (914) 736-8340
 IPN-96-028
 ATTACHMENT I
 PAGE 1 of 4

OPERATING STATUS

1. Unit Name: Indian Point No. 3 Nuclear Power Plant
2. Reporting Period: February 1996
3. Licensed Thermal Power (MWt): 3025
4. Nameplate Rating (Gross MWe): 1013
5. Design Electrical Rating (Net MWe): 965
6. Maximum Dependable Capacity (Gross MWe): 1000
7. Maximum Dependable Capacity (Net MWe): 965
8. If Changes Occur in Capacity Ratings (Items Number 3 through 7) Since Last Report Give Reasons: _____
9. Power Level to Which Restricted, If Any (Net MWe): _____
10. Reasons for Restrictions, If Any: _____

	This Month	Yr-to-Date	Cumulative
11. Hours In Reporting Period	696	1440	171,073
12. Number Of Hours Reactor Was Critical	0	0	93,763.53
13. Reactor Reserve Shutdown Hours	0	0	0
14. Hours Generator On-Line	0	0	91,160.83
15. Unit Reserve Shutdown Hours	0	0	0
16. Gross Thermal Energy Generated (MWH)	0	0	258,728,881
17. Gross Electrical Energy Generated (MWH)	0	0	80,919,905
18. Net Electrical Energy Generated (MWH)	0	0	77,828,663
19. Unit Service Factor	0	0	53.3
20. Unit Availability Factor	0	0	53.3
21. Unit Capacity factor (Using MDC Net)	0	0	48.2*
22. Unit Capacity Factor (Using DER Net)	0	0	47.1
23. Unit Forced Outage Rate	100	100	30.9

24. Shutdowns Scheduled Over Next 6 Months (Type, Date and Duration of Each):

25. If Shut Down At End Of Report Period. Estimated Date of Startup: March 24, 1996
 26. Units In Test Status (Prior to Commercial Operation):

	Forecast	Achieved
INITIAL CRITICALITY	_____	_____
INITIAL ELECTRICITY	_____	_____
COMMERCIAL OPERATION	_____	_____

* Weighted Average

AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-286
 UNIT IP-3
 DATE 3-5-96
 COMPLETED BY T. Orlando
 TELEPHONE (914) 736-8340
 IPN-96-028
 ATTACHMENT I
 PAGE 2 of 4

MONTH FEBRUARY, 1996

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	0	17	0
2	0	18	0
3	0	19	0
4	0	20	0
5	0	21	0
6	0	22	0
7	0	23	0
8	0	24	0
9	0	25	0
10	0	26	0
11	0	27	0
12	0	28	0
13	0	29	0
14	0	30	-----
15	0	31	-----
16	0		

INSTRUCTIONS:

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-286
 UNIT NAME INDIAN POINT NO. 3
 DATE 3-5-96
 COMPLETED BY T. Orlando
 TELEPHONE (914) 736-8340
 IPN-96-028
 ATTACHMENT I
 PAGE 3 of 4

REPORT MONTH FEBRUARY 1996

NO.	DATE	TYPE 1	DURATION (HOURS)	REASON 2	METHOD OF SHUTTING DOWN REACTOR 3	LICENSEE EVENT REPORT #	SYSTEM CODE 4	COMPONENT CODE 5	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
1	950914	F	696	A	1	95-18-00	XX	GENERA X	THE REACTOR WAS MANUALLY SHUTDOWN AND THE TURBINE AUTOMATICALLY SHUTDOWN DUE TO A HIGH MAIN GENERATOR STATOR TEMPERATURE DIFFERENTIAL (DELTA T) DURING A CONTROLLED UNIT SHUTDOWN. THIS SHUTDOWN WAS REQUIRED TO REPAIR A HYDROGEN LEAK IN THE UNITS MAIN GENERATOR. THE OUTAGE WAS EXTENDED TO FACILITATE REPAIRS TO OTHER PLANT SYSTEMS.

1
 F: Forced
 S: Scheduled

2
 Reason:
 A-Equipment
 B-Maintenance or Test
 C-Refueling
 D- Regulatory Restriction

3
 Method
 1-Manual
 2-Manual Scram
 3-Automatic Scram
 4-Other (Explain)

4
 Exhibit - Instructions
 for Preparation of Data
 Entry Sheets for Licensee
 Event Report (LER) File
 (NUREG - 0161)

5
 Exhibit - Same Source

SUMMARY OF OPERATING EXPERIENCE

FEBRUARY 1996

While in cold shutdown on January 20, 1996, at approximately 1845 hours, the unit experienced a loss of 138 Kv supply power to the Station Auxiliary Transformer (LOOP). All three Emergency Diesel Generators (EDG) automatically started as required by sensing the undervoltage conditions on the 480 volt safeguards buses. However, shortly after starting, the output breaker for loading EDG 31 to its assigned 480 volt safeguard bus tripped open rendering EDG 31 inoperable. EDG 32 and EDG 33 successfully started and their associated output breakers closed in and powered their assigned 480 volt safeguard buses. However, after offsite power was restored EDG 32 was declared inoperable at approximately 2229 hours, when an operator discovered the EDG 32 room ventilation was not operating as required. Declaring EDG 32 inoperable along with an inoperable EDG 31 placed the plant in violation of Technical Specifications Section 3.7.F.4 which requires two EDGs to be operable in cold shutdown. Upon investigation it was determined that there was insufficient air pressure to the room's ventilation system to operate as required. The pressure regulator for the ventilation system was replaced. The ventilation system was repaired, and tested and placed in service restoring EDG 32 to an operable status. This event was reported in LER 96-002-00.

Investigation of the event discovered that the cause of the LOOP was a faulted phase gap-type surge arrester on Phase A of the Station Auxiliary Transformer. The arrester faulted as a result of moisture intrusion through a caulked seal in the arrester's upper cover.

Results of troubleshooting and testing of EDG-31 and its output breaker indicated that the cause of the breaker to open shortly after closing was caused by a loose wire termination in a seal-in contact relay in the EDG undervoltage circuit.

A failure investigation of the air regulator determined that rust was the cause of the improper operation. Due to these events, the unit remained off line for the entire reporting period.

Following successful completion of repairing and retesting the above mentioned plant equipment, the unit began preparations for unit restart. On February 25, at 0239 hours, the unit was taken above the cold shutdown condition to the hot shutdown condition and remained in hot shutdown for the remainder of the reporting period.