

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



Robert J. Barrett
Site Executive Officer

June 6, 1997
IPN-97-073

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
Licensee Event Report # 97-006-00
**Plant Outside Design Basis Due to Error In Original Design That
Did Not Identify RWST Purification Loop Isolation Requirements**

Dear Sir:

The attached Licensee Event Report (LER) 97-006-00 is submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(ii)(B).

Also attached are the commitments made by the Authority in this LER.

Very truly yours,

A handwritten signature in black ink, appearing to read 'Robert J. Barrett', written over a horizontal line.

Robert J. Barrett
Site Executive Officer
Indian Point 3 Nuclear Power Plant

Attachment

cc: See next page

9706170285 970606
PDR ADOCK 05000286
S PDR



160116

//
Jerr

cc: Mr. Hubert J. Miller
Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania. 19406-1415

INPO Record Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant

Commitment List

Number	Commitment	Due
IPN-97-073-01	An extent of condition review is in progress to determine whether other non-seismic systems that are connected to seismic systems during normal operation could cause or increase the severity of a LOCA. If additional interface problems are identified, action will be initiated to update this LER.	Prior to Startup