Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 736.8001



August 20, 1997 IPN-97-110

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

SUBJECT: Indian Point 3 Nuclear Power Plant Docket No. 50-286 License No. DPR-64 Licensee Event Report # 97-013-00 Operation of 2 High Head Safety Injection Pumps, a Condition Prohibited by Technical Specification, Due to Personnel Error

Dear Sir:

The attached Licensee Event Report (LER) 97-013-00 is hereby submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(i)(B).

Also attached are the commitments made by the Authority in this LER.

Very truly yours, otsek Robert J Bárreit

Site Executive Officer Indian Point 3 Nuclear Power Plant

cc: See next page

9709020213 970820 PDR ADUCK 05000286 S PDR

020000

Robert J. Barrett Site Executive Officer

TÊGÔ

Docket No. 50-286 IPN-97-110 Page 2 of 2

cc: Mr. Hubert J. Miller
Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission Resident Inspectors' Office Indian Point 3 Nuclear Power Plant

Docket No. 50-286 IPN-97-110 Attachment I Page 1 of 1

Commitment List

Number	Commitment	Due
IPN-97-110-01	IP3 TSIs have been reviewed and TSIs that do not comply have been scheduled for withdrawal.	Six months after end of current refueling outage
IPN-97-110-02	A proposed revision to Technical Specification 3.3.A.8 will be submitted to allow two HHSI pumps to be operated where required.	Nine months after end of current refueling outage
IPN-97-110-03	The IP3 TSIs scheduled for withdrawal will be annoted until withdrawn.	September 17, 1997
IPN-97-110-04	AP 18.7 will be revised to provide criteria for TSIs.	Six months after end of current refueling outage