

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



Robert J. Barrett
Site Executive Officer

October 6, 1997
IPN-97-137

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555


SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
Licensee Event Report # 97-022-00
Two Safety Injection Pumps Inoperable During a Design
Basis Event May Have Placed the Plant Outside Design
Basis Due to Inadequate Procedural Instructions

Dear Sir:

The attached Licensee Event Report (LER) 97-022-00 is hereby submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a) (2) (ii) (B).

Also, attached is the commitment made by the Authority in this LER.

Very truly yours,

FOR. 
Robert J. Barrett
Site Executive Officer
Indian Point 3 Nuclear Power Plant

///
Lezz

Attachment

cc: See next page

100000



9710150200 971006
PDR ADOCK 05000286
S PDR

cc: Hubert J. Miller
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant

COMMITMENT LIST

Number	Commitment	Due
IPN-97-137-01	The EOP verification and validation process will be revised to include a requirement to coordinate between procedures to ensure system pre-requisites, such as valve alignment.	January 19, 1998
IPN-97-137-02	The lessons learned from this event will be reviewed with operations procedure writers and operations training personnel.	November 17, 1997