

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



Robert J. Barrett
Site Executive Officer

October 9, 1997
IPN-97- 139

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555


SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
Licensee Event Report # 97-024-00
**Reactor Trip Due to a Turbine Trip as a Result of a Personnel
Error During Turbine Generator Mechanical Trip Testing**

Dear Sir:

The attached Licensee Event Report (LER) 97-024-00 is hereby submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(iv).

Also attached are the commitments made by the Authority in this LER.

Very truly yours,

For 
Robert J. Barrett
Site Executive Officer
Indian Point 3 Nuclear Power Plant

cc: See next page

9710210166 971009
PDR ADOCK 05000286
S PDR



10/22
11

cc: Mr. Hubert J. Miller
Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant

Commitment List

Number	Commitment	Due
IPN-97-139-01	An analysis will be performed to determine the cause of the procedural error.	October 31, 1997
IPN-97-139-02	An analysis will be performed to determine the cause of the failure of the operating crew to detect the change in status of permissives P-7 and P-10.	October 31, 1997