Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 736,8001



March10, 1998 IPN-98-030

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

SUBJECT:

Indian Point 3 Nuclear Power Plant Docket No. 50-286 License No. DPR-64 Licensee Event Report # 97-013-01 Operation of 2 High Head Safety Injection Pumps, a Condition Prohibited by Technical Specification, Due to Personnel Error

Robert J. Barrett Site Executive Officer-

Dear Sir:


The attached Licensee Event Report (LER) 97-013-01 is a revision to clarify the corrective actions being taken and make several editorial corrections.

Also attached are the commitments made by the Authority in this LER.

Very truly yours ant (A

Robert J. Barrett Site Executive Officer Indian Point 3 Nuclear Power Plant

cc: See next page



Docket No. 50-286 IPN-98-030 Page 2 of 2

Mr. Hubert J. Miller Regional Administrator Region I U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406-1415

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission Resident Inspectors' Office Indian Point 3 Nuclear Power Plant

cc:

Docket No. 50-286 IPN-98-030 Attachment I Page 1 of 1

Commitment List

•

Number	Commitment	Due
IPN-98-030-01	IP3 TSIs have been reviewed and TSIs that do not comply with NYPA revised criteria for TSI issuance (based on recent NRC guidance) have been identified and planned actions are in place to assure TSIs comply with NYPA criteria.	During TS or Bases implementation.
IPN-98-030-02	Procedure AP 18.7 will be revised to provide criteria for TSIs and the prior review will be finalized based on the approved guidance.	June 15, 1998